

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	7504	(monitor\$3 or detect\$3 or sens\$3) near4 (air or pressure) near3 (tire or pneumatic)	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 13:55
L2	417744	(pin or plung\$3 or switch\$3) near4 (depress\$3 or manual\$2 or rotat\$3 or press\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 13:59
L3	16579	2 near9 (sequence or order or cycle)	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:00
L4	222	(identif\$4 or learn\$3 or recogniz\$3) near5 ((location or position) near4 (tire or pneumatic))	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:01
L5	0	3 with 4	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:01
L6	1	3 same 4	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:02
L7	9	1 and 3 and 4	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:14
L8	7	7 and magnet\$4	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:16
L10	2	7 and (plung\$3 or depress\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:22
L11	4	(("5963128") or ("6856245")).PN.	USPAT; EPO; JPO; DERWENT	OR	OFF	2005/08/30 14:25
L12	0	3 and 4 and 11	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:26
L13	0	3 and 11	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:25
L14	1	4 and 11	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:25
L15	1	2 and 4 and 11	USPAT; EPO; JPO; DERWENT	OR	ON	2005/08/30 14:26